25X1 CLASSIFICATION S-E-C-N-E-T/NOFORM REPORT CENTRAL INTELLIGENCE AGENCY INFORMATION REPORT CD NO. DATE DISTR. 1 December 1955 COUNTRY East Germany NO. OF PAGES Shortage of Revlacement Parts at Berlin SUBJECT Rummelsburg Tower Station NO. OF ENCLS. (LISTED BELOW) 25X1 **ACQUIRED** SUPPLEMENT TO DATE OF REPORT NO.

this document contains information affecting the national defe CODE, AS ARENDED. ITS TO OR RECEIPT BY AR THE REPRODUCTION OF T CTION OF THIS FORM IS PRONIBITED

1.

 $\mathcal{F}_{\mu}$ 

PLACE.

INFO.

## THIS IS UNEVALUATED INFORMATION

25X1

an average steam pressure of 30 atmospheres were available at the Rummelsburg power station. Approximately one third of them was not in use because they could not be repaired for lack of material. The remaining boilers which were also unreliable were operated on the basis of a two-year special permission.

**ILLEGIB** 

**ILLEGIB** 

- The power plant was in great need of safety and desalting valves which were produced by the VEE Messgeraete- und Armaturenwerk Karl Marx (Schaeffer & Budenberg) (Nationalized Firm for the Production of Measuring and Control Devices) in Mandahuro-Ruckau. As a rule 50 percent of the valves supplied were unusable because they had scabs. The material required for welding these scabes is in most cases not available; as a result that the valves cracked after being put into operation. The testing of the valves in the manufacturing firm was carried out by the cold water pressure system instead of by the petroleum pressure method as required. Moreover, the high-quality, acid-resisting material needed for the manufacture of desalting valves was not available and substitutes had to be used. The loss of dehydrating and desludging valves was approximately 10 percent. Faulty valves were not replaced by the manufacturing firm, because a higher production than originally fixed was not scheduled.
- There was also a bottleneck in boxler tubes. For example, a 4-meter long tube with a diameter of 35.8 cm was required for repairing one of the boilers. When it turned out that it was nowhere obtainable, two shorter tubes with different diameters were welded together. Such provisional measures led to tube damage.

25X1

CLASSIFICATION S-E-C-R-E-T/NUPORN STATE NAVY NSRB DISTRIBUTION ARMY V AIR FBI